


⚠ WARNING

All electrical repairs to this line trimmer, including housing, switching, motor, etc., must be diagnosed and repaired by qualified service personnel. Failure to do so could cause the double insulation construction to become ineffective and result in serious personal injury.



Ref #	Part Number	Qty	Description
1	530092678	1	Motor Housing Set
2	530092679	6	Screw
3	530090827	2	Screw
4	530092049	1	Wing Nut
5	530092681	1	Tube Clamp Bushing
6	530092682	1	Clamp
7	530092683	1	Screw
8	530093856	1	Power Cord
9	530090824	1	Switch
10	530092684	1	Drive Coupling
11	530092685	1	Collar
12	530092686	2	Screw
13	530092687	1	559 Electric Trim Page 2 of 2 Lube Connector
14	530092688	2	TRIMMER ASSEMBLY Screw
15	530092689	1	Motor Assembly
16	530091402	1	Grip
17	530091802	1	Handle Bar
18	530091338	2	Clamp
19	530091342	1	Bolt
20	530091816	1	Handle Bar Plug
21	530091301	1	Drive Shaft Housing
22	530092261	1	Drive Shaft
23	530091341	1	Washer
24	530091339	1	Knob
25	530091979	1	Shield
26	530092049	1	Wing Nut
27	530092062	1	Flat Washer
28	530092061	1	Bolt
29	530015518	1	Screw
30	530091315	1	Bearing Housing
31	530091316	2	Bearing
32	530091317	1	Spacer
33	530092692	1	Retaining Ring
34	530091319	1	Arbor Shaft
35	530091318	1	Retaining Ring
36	530091322	1	Woodruff Key
37	530091323	1	Dust Cover
38	530093894	1	Cutting Head Assembly New Style
38		1	Cutting Head Assembly Old Style
39	530092064	1	Bolt - Drive Adaptor - Old Style
40	530092131	1	Hub w/Line Savers - Old Style
40	530093896	1	Hub w/Line Savers - New Style
41	530092067	1	Coil Spring
42	530092068	1	Coil Spring Adaptor
43	530092069	1	Drive Gear Old Style
43	530093897	1	Drive Gear New Style
44	952701523	1	Spool, Wound
45	530093387	1	Release Button
46	530092133	1	Cover
47	530093898	1	Line Saver - New Style only